Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC.
Well Operator: EOG RESOURCES, INC.
Well Name: CLEARWATER 200-06 SWD

Field Name: CLEAR WATER Well File #: 90180

Date Incident: 3/10/2015 Time Incident: 17:30 Facility ID Number:

County: MOUNTRAIL Twp: 157 Rng: 90 Sec: 6 Qtr: SW SE

Location Description:

Submitted By: Keith Kallberg Received By:

Contact Person: Keith Kallberg

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Valve/Piping Connection Leak

Release Contained in Dike Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 20 Barrels 20 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

N/A

Tuesday, March 24, 2015 Page 1 of 2

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The system was shutin, to stop the release and repair the leak. Vac truck was used to remove the free fluid that had been diluted with fresh water from the snow melt inside the containment, total bbls of fluid removed was 76 bbls.

Wastes Disposal Location: Fluids were taken to an offload tank at the Sidonia 9-35H and

transfered to Sidonia SWD by pipeline.

Agencies Involved:

Updates

Date: 3/11/2015 Status: Reviewed; O&G Lead Staff: Stockdill, Scott

Status. Neviewed, Odo Lead

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Tuesday, March 24, 2015 Page 2 of 2